

PPE Selector - - Objectives

Objectives

- Explain why electrical contractors should follow precautions set forth in NFPA 70E
- List at least three hazards which demonstrate why a flash hazard analysis is needed.
- Describe the restrictions associated with the boundaries defined in NFPA 70E.
- Identify two methods for determining the appropriate PPE for a given task
- Given the Hazard Risk Category of a task select appropriate PPE.

PPE Selector – Summary of NFPA 70E Standard

NFPA 70E - 2009

Chapter 1 - Safety- Related Work Practices

Chapter 2 - Safety-Related Maintenance Requirements

Chapter 3 - Safety Requirements for Special Equipment.



© 2009 National Electrical Contractors Association and Intec, Inc.

Summary of NFPA 70E Standard for Electrical Safety in Workplace


PPE Compliance/Advice

- OSHA
 - 1910 General Industry Subpart S
 - 1926 Construction Subpart K
- NFPA 70E

- OSHA THE TOTAL PROPERTY OF THE PARTY OF THE
- OSH Act: General Duty Clause 5a(1)
- Other

PPE Selector – Assessment

The Body as Conductor



Current (mA*)	Reaction
1	Faint tingle
5	Slight shock
6 – 30	Can't let go
50 – 150	Death possible
1,000 – 4,300	Heart ceases

^{*} mA = 0.001 amp


© 2009 National Electrical Contractors Association and Intec, Inc.


PPE Selector – Assessment

Protect Employees

- Working on or Near Live Parts
 - Justification
 - Safe Practices for Working Hot
- Personal Protective Equipment







PPE Selector – Assessment

Assess Hazards - Electrical Hazard Analysis

• Flash Hazard Analysis

Flash Boundary =

$$D_c = [2.65 \times MVA_{bf} \times f]^{1/2}$$


$$D_c = [53 \times MVA \times t]^{1/2}$$

© 2009 National Electrical Contractors Association and Intec, Inc.

PPE Selector – Assessment

Assess Hazards - Electrical Hazard Analysis

Flash Hazard Analysis



PPE Selector – Assessment


Assess Hazards - Electrical Hazard Analysis

• Flash Hazard Analysis

Greater than 600 volts = Distance at which **Incident Energy** Equals 1.2 cal/cm^{2*}

SEE Table D.2

*(Fault clearing time slower than 0.1. seconds)



© 2009 National Electrical Contractors Association and Inter-

PPE Selector – Assessment

Incident Energy Levels

Levels of Exposure

Levels of Exposure		
Hazard Risk Category	Minimum ATPV Rating	
Category 0	(N/A)	
Category 1	4	
Category 2	8	
Category 3	25	
Category 4	40	
No Category – Not Permitted		
	Hazard Risk Category Category 0 Category 1 Category 2 Category 3 Category 4	

PPE Selector - Selection

Calculation Method


- Calculate Incident Energy Level (cal/cm²)
- Select the Hazard / Risk Category using Table 130.7(C)(11)
 (Match PPE Arc Thermal Protective Value (ATPV) to incident energy calculation)
- Select clothing and PPE for task from Table 130.7(C)(10)
- Determine the need for V-rated gloves and tools


© 2009 National Electrical Contractors Association and Intec, Inc.


PPE Selector - Selection


Table Method


- Identify Hazard / Risk Category Classification in Table 130.7(C)(9)
- Select clothing and PPE from Table 130.7(C)(10) and the need for V- rated gloves and tools














PPE Selector - Selection

Basic Rules of PPE

- Layering
- Coverage
- Fit
- Maintenance



© 2009 National Electrical Contractors Association and Intec, Inc.

PPE Selector – Tools and Equipment

Supplemental Protective Equipment


- Tools
- Temporary grounds
- Rubber insulating equipment
- Barriers
- Inspection and maintenance



PPE Selector – Summary

NFPA 70E Requirements

- Complete Energized Electrical Work Permit
- Perform Hazard/Risk Analysis
- Select PPE



© 2009 National Electrical Contractors Association and Intec, Inc.

PPE Selector – Summary

Exceptions to Work Permit by Qualified Person

- Testing
- Troubleshooting
- Voltage Measuring



PPE Selector - Summary

PPE

- Required within the Flash Protection Boundary
- Based on Flash Hazard Analysis as well as other hazards
- Includes head to toe protection



© 2009 National Electrical Contractors Association and Intec, Inc.

PPE Selector - Summary

Supplemental Protective Equipment

- Tools
- Temporary grounds
- Rubber insulating equipment
- Barriers
- Inspection and maintenance



PPE Selector – Review Questions

- 1. A prudent course of action for electrical contractors is to observe the PPE requirements in NFPA 70E because:
 - a. NFPA 70E is the equivalent of an OSHA standard
 - b. NFPA 70E serves as an industry guideline for safe practices and may be referenced by OSHA
 - c. NFPA 70E should not be used

© 2009 National Electrical Contractors Association and Intec, Inc.

PPE Selector - - Review Questions

2. List at least three hazards which demonstrate why a flash hazard analysis is needed

Electric Shock Hazard

Extreme Temperatures

Molten Metal Debris

Intense Light

Sound waves

Pressure

PPE Selector – – Review Questions

- 3. A distance from an exposed energized electrical conductor or circuit part within which a shock hazard exists is:
 - a. Arc Flash Protection Boundary
 - b. Limited Protection Boundary
 - c. Prohibited Boundary

© 2009 National Electrical Contractors Association and Intec, Inc

PPE Selector - - Review Questions

4. The only method for determining the appropriate PPE is to perform a Flash Hazard Analysis and Incident Energy Level calculation using appropriate formulas.

True

False

PPE Selector - - Review Questions

- 5. Which of the following would you not expect to be need for a Hazard Risk Category 0?
 - a. Arc-rated face shield or flash suit hood
 - b. Hearing
 - c. Rubber Gloves

© 2009 National Electrical Contractors Association and Intec, Inc

ACKNOWLEDGEMENTS

Program developed by:

Keith Williams and John Caporelli INTEC, INC.

PO Box 163 Waverly, PA 18471 www.intecweb.com

800.745.4818 Fax 800.949.1930

Photographs contributed by:

W.H. SALISBURY

7520 North Long Ave. Skokie, IL 60077 877.406.4501 Fax 866.824.4922 www.whsalisbury.com

Jeffery Morris, President jeff.morris@whsalisbury.com

Program edited by:

James B. Lancour, PhD jbl consulting and training jblancour@pngusa.net 678.457.6108

WORKRITE UNIFORM COMPANY

PO Box 1192 Oxnard, CA 93032 www.workrite.com 805.483.0175 Fax 805.487.5985

Janet Costa, Marketing Communication Manager jcosta@workrite.com.

